

BERRY PETROLEUM COMPANY LLC
CHEVRON 036A 596
Location # 335583



No evidence of tracking control BMP's

BERRY PETROLEUM COMPANY LLC
CHEVRON 036A 596
Location # 335583



No evidence of tracking control BMP's

BERRY PETROLEUM COMPANY LLC
CHEVRON 036A 596
Location # 335583



N39.55098 W-108.12060



Sediment blockage in ditch.

BERRY PETROLEUM COMPANY LLC
CHEVRON 036A 596
Location # 335583



N39.55348 W-108.11985



Water not draining off road.

BERRY PETROLEUM COMPANY LLC
CHEVRON 036A 596
Location # 335583



Sediment build up in culvert outlet.



Erosion damage from culvert outlet.

BERRY PETROLEUM COMPANY LLC
CHEVRON 036A 596
Location # 335583



Erosion damage from culvert outlet.



Erosion damage from culvert outlet.