

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/25/2021

Submitted Date:

01/25/2021

Document Number:

699502185**FIELD INSPECTION FORM**Loc ID 319999 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|----------------|--------------------------|---------------------------------|
| Ingvie, Ed | (303) 680-4725 | ed@renegadeoilandgas.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 202201 | WELL | PR | 12/01/2018 | GW | 001-07606 | UPRR 48 PAN AM H 1 | PR |

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 202201 Type: WELL API Number: 001-07606 Status: PR Insp. Status: PR

Workover

Comment: At time of inspection rig crew was in process of hydrotesting tubing POOH. Rods were hanging in derrick. Rig operator informed me they would lay down any tubing that had integrity issues. Operator informed me that they would RIH with new pump after service of well was complete.

Corrective Action:

Date:

COGCC Comments

| Comment | User | Date |
|---|---------|------------|
| <p>At time of inspection location appears to be in compliance with COGCC rules.</p> <p>At time of inspection weather conditions were cloudy, cold, windy.</p> <p>At time of inspection spoke with rig operator about driving inside guy lines of rig, rig operator informed me of dangers around workover activities. Spoke with rig operator about activities on site.</p> <p>Called emergency number concerning Foundation Energy Managemebt is listed as owner of well, and was informed that form 10 is in process of approval by company representative (Renegade oil and gas company)</p> <p>End of inspection.</p> | medinaj | 01/25/2021 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 699502186 | pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5336575 |