

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/26/2021

Submitted Date:

01/28/2021

Document Number:

700405211**FIELD INSPECTION FORM**Loc ID 316011 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 51130Name of Operator: LOCIN OIL CORPORATIONAddress: 2445 TECHNOLOGY FOREST BD #710City: THE WOODLANDS State: TX Zip: 77381**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Thompson, Bud		BLThomps@BLM.gov	
Nicol, Michael	281-362-8600x116	mnicol@locinoil.com	<a href="#">All inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231912	WELL	PR	09/01/1993	GW	103-09583	SOUTHWEST RANGELY FED 9-4-1-2X	PR

**General Comment:**

A routine inspection identified the following compliance issues:

1) Provide bradenhead access. Photo 3. Complete by 2-28-2021.

This is a summary of inspection report 700405211.

**Location**Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PIT		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment: Telemetry.			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment: Bradenhead access is not present.			
Corrective Action: Provide bradenhead access with appropriate fittings to allow determination of pressure and fluid flow.		Date: 02/28/2021	
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

--

Inspected Facilities									
Facility ID:	231912	Type:	WELL	API Number:	103-09583	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:				Date:					

## Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: 9" of snow on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NO

Pit ID:

Lat:

Long:

Reference Point: \_\_\_\_\_

Other: \_\_\_\_\_

Length: \_\_\_\_\_

Width: \_\_\_\_\_

**Lining:**

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**Fencing Type: WildlifeFencing Condition: Adequate

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700405212	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5339659">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5339659</a>