

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/29/2021

Submitted Date:

01/29/2021

Document Number:

699502201

FIELD INSPECTION FORMLoc ID 330987 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257529	WELL	PR	10/23/2000	OW	123-19990	ROCKY MOUNTAIN FUEL CO 15-9	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment: gas motor

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 257529 Type: WELL API Number: 123-19990 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Annual bradenhead test is not current. Contact COGCC engineering.02/08/2021Corrective Action: Comply with COGCC annual bradenhead testing rules.

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 1/29/21 at approximately 1230 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Rocky Mountain Fuel CO 15-9</p> <p>Company Name- KPK</p> <p>API- 05-123-19990</p> <p>In Weld County Colorado.</p> <p>While there, I observed PR well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Annual Bradenhead test is not current. Contact COGCC engineering.</p> <p>Comply with COGCC annual bradenhead testing rules. 2/8/21</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	01/29/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699502202	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5340854