

**TEP ROCKY MOUNTAIN LLC
FEDERAL-66S96W 34SWNE
Location # 335164**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present)**

**TEP ROCKY MOUNTAIN LLC
FEDERAL-66S96W 34SWNE
Location # 335164**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present)**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present)**

**TEP ROCKY MOUNTAIN LLC
FEDERAL-66S96W 34SWNE
Location # 335164**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present)**



No evidence of tracking control BMP's.

**TEP ROCKY MOUNTAIN LLC
FEDERAL-66S96W 34SWNE
Location # 335164**



**No evidence of tracking control BMP's.
Mud tracked on to CR 215.**

Mud tracked on to CR 215.