

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/25/2021

Submitted Date:

02/26/2021

Document Number:

699802665**FIELD INSPECTION FORM**Loc ID 334520 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**28 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Laramie		cogccnotifications@laramie-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291438	WELL	PR	07/01/2020	GW	077-09339	HAWKINS RANCH 10-3	PR
291441	WELL	PR	03/01/2017	GW	077-09338	HAWKINS RANCH 3-13	PR
291442	WELL	PR	08/31/2011	GW	077-09337	HAWKINS RANCH 10-4	PR
295761	WELL	PR	03/07/2010	GW	077-09626	HAWKINS RANCH 10-2B	PR
295762	WELL	PR	10/14/2013	GW	077-09625	HAWKINS RANCH 10-4A	PR
295763	WELL	PR	02/16/2010	GW	077-09624	HAWKINS RANCH 10-3C	PR
295764	WELL	PR	03/01/2010	GW	077-09623	HAWKINS RANCH 10-3B	PR
295766	WELL	PR	12/14/2009	GW	077-09621	HAWKINS RANCH 10-3A	PR
295767	WELL	PR	12/18/2009	GW	077-09620	HAWKINS RANCH 10-2A	PR
295768	WELL	PR	03/06/2010	GW	077-09619	HAWKINS RANCH 3-13C	PR
295769	WELL	PR	11/04/2013	GW	077-09618	HAWKINS RANCH 3-13B	PR
295770	WELL	PR	02/09/2016	GW	077-09617	HAWKINS RANCH 3-13A	PR
297455	WELL	PR	02/04/2010	GW	077-09693	HAWKINS RANCH 10-4B	PR
297456	WELL	PR	02/15/2010	OW	077-09694	HAWKINS RANCH 10-4C	PR

General Comment:

COGCC Inspection Report Summary

On Thursday 2/25/21 at approximately 15:00 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at LARAMIE ENERGY LLC Hawkins Ranch /10-4 Pad, Location #334520 in Mesa County Colorado.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: Sediment has been transported off of location due to snow plowing. See photo #2995, #2996, #2997, #2998 and #2999 with a corrective action date of 3/13/21.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Note there is no battery sign located at the battery. The previous information was posted at the entrance to location and does not meet the new battery sign requirements of Rule 605e.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Multiple wellhead signs weathered but are still legible		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:			
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed wire fence around location		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 7		

Comment:		Date:	
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 4		
Comment:		Date:	
Corrective Action:		Date:	
Type: Bradenhead	# 14		
Comment:	No form of pressure monitoring located on braden heads. All braden head valves are accessible.	Date:	
Corrective Action:		Date:	
Type: Gas Meter Run	# 14		
Comment:	All meter runs have been calibrated in the last year.	Date:	
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 12		
Comment:		Date:	
Corrective Action:		Date:	
Type: Plunger Lift	# 14		
Comment:	All wells on plunger lift	Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Centralized containment				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	291438	Type:	WELL	API Number:	077-09339	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	291441	Type:	WELL	API Number:	077-09338	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	291442	Type:	WELL	API Number:	077-09337	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	295761	Type:	WELL	API Number:	077-09626	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	295762	Type:	WELL	API Number:	077-09625	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	295763	Type:	WELL	API Number:	077-09624	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	295764	Type:	WELL	API Number:	077-09623	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	295766	Type:	WELL	API Number:	077-09621	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Facility ID: 295767	Type: WELL	API Number: 077-09620	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID: 295768	Type: WELL	API Number: 077-09619	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID: 295769	Type: WELL	API Number: 077-09618	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID: 295770	Type: WELL	API Number: 077-09617	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID: 297455	Type: WELL	API Number: 077-09693	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID: 297456	Type: WELL	API Number: 077-09694	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Other	Fail					Sediment transported due to plowing
Ditches						
		Sediment Traps				
Gravel						
		Gravel				
Berms						
		Berms				
		Ditches				

Comment: Sediment has been transported off of location due to snow plowing. See photo #2995, #2996, #2997, #2998 and #2999

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater in a manner that minimizes the transport of sediment offsite.

Date: 03/13/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	414313	1630257	
	414313	1630257	

COGCC Comments

Comment	User	Date
Refer to Storm water for corrective actions.	depaoloc	02/26/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699802666	Photos for Insp. #699802665	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5362584