

BERRY PETROLEUM COMPANY LLC
CHEVRON K17 696
Location ID: 335596



BERRY PETROLEUM COMPANY LLC
CHEVRON K17 696
Location ID: 335596



Ditch on road needs maintained.



Ditch coming off location around entrance corner needs maintained.

BERRY PETROLEUM COMPANY LLC
CHEVRON K17 696
Location ID: 335596



Ditch at main road and access road needs maintained.



Ditch at main road and access road needs maintained.

BERRY PETROLEUM COMPANY LLC
CHEVRON K17 696
Location ID: 335596



Ditch on main road needs maintained.



Ditch on main road needs maintained.

BERRY PETROLEUM COMPANY LLC
CHEVRON K17 696
Location ID: 335596



Culvert just before main road and access road intersection needs maintained.



Culvert coordinates 39.52242 108.13237

BERRY PETROLEUM COMPANY LLC
CHEVRON K17 696
Location ID: 335596



Culvert just before main road and access road intersection needs maintained.



Culvert coordinates 39.52242 108.13237