

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402624898

Date Received:  
03/10/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Sanford, Anita</u>		<u>atlx@chevron.com</u>
<u>Olson, Andrew</u>		<u>andrewolson@chevron.com</u>
<u>Patterson, Chris</u>		<u>spwu@chevron.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202352

Inspection Date: 02/19/2021

FIR Submit Date: 02/23/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

LOCATION - Location ID: 398284

Location Name: CARNEY-62N102W Number: 35SENW County: \_\_\_\_\_

Qtrqtr: SENW Sec: 35 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.101929 Longitude: -108.814454

FACILITY - API Number: 05-103-00 Facility ID: 398284

Facility Name: CARNEY-62N102W Number: 35SENW

Qtrqtr: SENW Sec: 35 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.101929 Longitude: -108.814454

CORRECTIVE ACTIONS:

1 CA# 146804

Corrective Action: Comply with 1004 Rules: Remove debris and conduct additional reclamation activities; Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local soil conservation district. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed.

Date: 04/15/2021

Response: CA COMPLETED

Date of Completion: 03/10/2021

Operator Comment: Cleaned, seeded and BMP's installed. Will monitor vegetation. Please see attached photos

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**2** CA# 146805

Corrective Action: Comply with Rule 1002.f.(2) and install required stormwater and erosion control BMPs; ensure control measures are adequate for the site's conditions, installed in accordance with good engineering practices, and are maintained in a proper functioning condition. Ongoing stormwater management required until Location receives a passing final inspection.

Date: 03/10/2021

Response: CA COMPLETED

Date of Completion: 03/10/2021

Operator Comment: Installed required stormwater and erosion control BMPs Please see attached photo

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

OPERATOR COMMENT AND SUBMITTAL

Comment: Cleaned, seeded and BMP's installed. Will monitor vegetation. Please see attached photos  
Installed required stormwater and erosion control BMPs

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Patterson

Signed: \_\_\_\_\_

Title: Lead ENV Specialist

Date: 3/10/2021 3:05:45 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
402624907	Photo 1
402624908	Photo 2

Total Attach: 2 Files