

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402620622

Date Received:
03/08/2021

FIR RESOLUTION FORM

Overall Status: BOTH

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

- 1 CA Completed
- 1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10330
 Name of Operator: INVESTMENT EQUIPMENT LLC
 Address: 412 W PLATTE AVE
 City: FT MORGAN State: CO Zip: 80701

Contact Name and Telephone:
 Name: _____
 Phone: () _____ Fax: () _____
 Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>CHISHOLM JR. JAMES</u>	<u>405-642-9437</u>	<u>investmentequipment@gmail.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 690201230
 Inspection Date: 03/03/2021 FIR Submit Date: 03/05/2021 FIR Status: _____

Inspected Operator Information:

Company Name: INVESTMENT EQUIPMENT LLC Company Number: 10330
 Address: 412 W PLATTE AVE
 City: FT MORGAN State: CO Zip: 80701

LOCATION - Location ID: 321099

Location Name: TANNER SECU-635S46W Number: 2SESE County: BACA
 Qtrqr: SESE Sec: 2 Twp: 35S Range: 46W Meridian: 6
 Latitude: 37.019510 Longitude: -102.563280

FACILITY - API Number: 05-009-00 Facility ID: 206037

Facility Name: TANNER SECU Number: 401
 Qtrqr: SESE Sec: 2 Twp: 35S Range: 46W Meridian: 6
 Latitude: 37.019510 Longitude: -102.563280

CORRECTIVE ACTIONS:

1 CA# 147189

Corrective Action: Comply with 1004 Rules
Remove all equipment and debris.

Date: 02/20/2021

Response: CA COMPLETED Date of Completion: 04/30/2021

Operator Comment: Small amount of equipment left on location will be removed in April.

COGCC Decision: **Not Approved**

COGCC Representative: Not approved. Corrective action is not completed. All equipment should have been removed within 3 months of abandoning the well. The location remains out of compliance with rule 1004.

COGCC Supervisor: Not approved. Corrective action is not completed. All equipment should have been removed within 3 months of abandoning the well. The location remains out of compliance with rule 1004.

2  CA# 147190

Corrective Action: Submit form 27 for pit closure.
Contact COGCC EPS staff for directives.

Date: 05/06/2015

Response: FACTUAL REVIEW REQUEST

Basis for Review: Action requested was already completed prior to the inspection

Operator Comment: The pit in question has never been owned by Investment Equipment. This pit belongs to the landowner per the attached document that had been submitted and approved by the COGCC in 2016.

COGCC Decision: **Not Approved**

COGCC Representative: Not approved. The pit was documented in the 1986, 1998, and 2015 inspections. The pit is visible in 1988, 1998, 2005, 2006, 2011, 2013, and 2016 aerial images. The pit was associated with the oil and gas location and will need to be reclaimed per the 1004 rules. All trash and debris will need to be removed from the pit and properly disposed. The tank will require a variance if left on location with proof the tank was cleaned out.

COGCC Supervisor: Not approved. The pit was documented in the 1986, 1998, and 2015 inspections. The pit is visible in 1988, 1998, 2005, 2006, 2011, 2013, and 2016 aerial images. The pit was associated with the oil and gas location and will need to be reclaimed per the 1004 rules. All trash and debris will need to be removed from the pit and properly disposed. The tank will require a variance if left on location with proof the tank was cleaned out.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jim Chisholm

Signed: _____

Title: Manager / Member

Date: 3/8/2021 10:08:58 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402620622	FIR RESOLUTION SUBMITTED
402620701	COGCC accepted letter from Landowner

Total Attach: 2 Files