

TEP ROCKY MOUNTAIN LLC
PA 24-32
Location # 323949



Sign not at tank battery.

TEP ROCKY MOUNTAIN LLC
PA 24-32
Location # 323949



Location lacks stabilization.

TEP ROCKY MOUNTAIN LLC
PA 24-32
Location # 323949



Location lacks stabilization.

Location lacks stabilization.

**TEP ROCKY MOUNTAIN LLC
PA 24-32
Location # 323949**



Location lacks stabilization.



Location lacks stabilization.

TEP ROCKY MOUNTAIN LLC
PA 24-32
Location # 323949



**Storm water moving sediment off location
behind separator and tank.**