

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Report Date
03/16/2021

Document Number
402628541

OPERATOR'S MONTHLY REPORT OF OPERATIONS
ERROR REPORT

OPERATOR INFORMATION

OGCC Operator Number: <u>10749</u>	Contact Name and Telephone:
Name of Operator: <u>SIMCOE LLC</u>	Name: <u>Barbara Davis</u>
Address: <u>THREE ALLEN CENTER, 333 CLAY ST SUITE 3900</u>	Phone: <u>(346) 3482658</u> Fax: <u>()</u>
City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77002</u>	Email: <u>bdavis@ikavenergy.com</u>

Summary Totals:

Total Error(s): 10 Total Modified(s): 1 Total Deleted(s): 0

Total 10 Error(s)

Report Month/Year: 01/2021

#170	067-09963-00	HORTHER 31-03 #3	FRLDC	PR	[qtrqtr] QQ/SEC/TWP/RANGE NOT FOUND OR IS NULL	Comment: INCORRECT LOCATION. CHANGE LOCATION TO: Lot 3 30 33N 6W
#187	067-10003-00	STATE MZ #2	FRLD	PR	[qtrqtr] QQ/SEC/TWP/RANGE NOT FOUND OR IS NULL	Comment: INCORRECT LOCATION. CHANGE LOCATION TO: LOT 4 7 34N 6W
#188	067-10004-00	TIFFANY #4-1	FRLDC	PR	[qtrqtr] QQ/SEC/TWP/RANGE NOT FOUND OR IS NULL	Comment: INCORRECT LOCATION. CHANGE LOCATION TO: Lot 3 19 33N 6W
#189	067-10005-00	TIFFANY #4-3	FRLDC	PR	[qtrqtr] QQ/SEC/TWP/RANGE NOT FOUND OR IS NULL	Comment: INCORRECT LOCATION. CHANGE LOCATION TO: Lot 3 19 33N 6W
#190	067-10006-00	TIFFANY #4-2	FRLDC	PR	[qtrqtr] QQ/SEC/TWP/RANGE NOT FOUND OR IS NULL	Comment: INCORRECT LOCATION. CHANGE LOCATION TO: Lot 3 19 33N 6W
#213	067-06461-00	SOUTHERN UTE 33-10; #19-2	FRLDC	PR	[formation_code] WELL DOES NOT MATCH OPERATOR	Comment: INCORRECT SIDETRACK. CHANGE SIDETRACK FROM 00 TO 01
#252	067-06754-00	SOUTHERN UTE 32-9; #16-1	FRLDC	PR	[formation_code] WELL DOES NOT MATCH OPERATOR	Comment: INCORRECT SIDETRACK. CHANGE SIDETRACK FROM 00 TO 01
#257	067-06346-00	SOUTHERN UTE 32-9; #14-4	FRLDC	PR	[formation_code] WELL DOES NOT MATCH OPERATOR	Comment: INCORRECT SIDETRACK. SIDETRACKS 00 AND 01 WERE ABANDONED. CHANGE SIDETRACK FROM 00 TO 02.

#260 067-09327-00 RONALD REA #4 FRLDC PR

[formation_code] WELL DOES NOT MATCH OPERATOR Comment: INCORRECT SIDETRACK. SIDETRACK 00 WAS NEVER COMPLETED. CHANGE SIDETRACK FROM 00 TO 01.

#261 067-06383-00 SOUTHERN UTE 32-9; #21-2 FRLDC PR

[formation_code] WELL DOES NOT MATCH OPERATOR Comment: INCORRECT SIDETRACK. SIDETRACK 00 WAS ABANDONED AND NEVER COMPLETED. CHANGE SIDETRACK FROM 00 TO 01.

Total 1 Modified(s)

Report Month/Year: 01/2021

#274 067-06067-00 CRAIG #1 (24-33N-10W) FRLDC PR

[MODIFIED] MODIFIED Comment:

Total 0 Deleted(s)

Report Month/Year: /

#

[] Comment: