

TEP ROCKY MOUNTAIN LLC PA 22-34 Production Facility Location # 444624



Battery sign is not at tank battery.



**TEP ROCKY MOUNTAIN LLC
PA 22-34 Production Facility
Location # 444624**



South west separator unit isn't level.



**TEP ROCKY MOUNTAIN LLC
PA 22-34 Production Facility
Location # 444624**



**TEP ROCKY MOUNTAIN LLC
PA 22-34 Production Facility
Location # 444624**

