

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Plunger Lift

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: automation

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 202576 Type: WELL API Number: 001-07981 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well has been shut in since 6/1/18, needs MIT according to COGCC Mechanical Integrity Test rules.

Corrective Action: Well must be either:
1) Per COGCC Rule 326.b.(1) a successful mechanical integrity test shall be performed on each shut-in well within two (2) years of the initial shut-in date or
2) Be properly plugged and abandoned . Shut-in and temporarily abandoned wells must be properly reported on COGCC Form 7, Operator's Monthly Production Report.

Date: 03/29/2021

BradenHead

Date of Last Brhd Test: 12/11/2019 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Annual bradenhead test is not current. Contact COGCC engineering.

Date: 04/08/2021

Corrective Action: Comply with COGCC annual bradenhead rules.

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 3/29/21 at approximately 1400 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- C Lisco 14-21 Company Name- Behrens Resources INC. API- 05-001-07981 In Adams County Colorado. While there, I observed SI well. During this inspection the following possible compliance issues were observed: Annual bradenhead test is not current. Contact COGCC engineering. Comply with COGCC annual bradenhead testing Rules 4/8/21 Well has been shut in since 6/1/18, needs MIT according to COGCC Mechanical Integrity Test rules. Well must be either: 1) Per COGCC Rule 326.b.(1) a successful mechanical integrity test shall be performed on each shut-in well within two (2) years of the initial shut-in date or 2) Be properly plugged and abandoned . Shut-in and temporarily abandoned wells must be properly reported on COGCC Form 7, Operator's Monthly Production Report. 3/29/21 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. At time of inspection inspection pictures were taken outside of Colorado Air and Space Port fencing. Good housekeeping was observed from a distance. This is a summary of inspection report.</p>	medinaj	03/29/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699502430	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5389275