

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/01/2021

Submitted Date:

04/01/2021

Document Number:

699502494

FIELD INSPECTION FORMLoc ID 319762 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 31257

Name of Operator: FRITZLER RESOURCES INC

Address: P O BOX 114

City: FORT MORGAN State: CO Zip: 80701

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Fritzler, Gene	970-768-0845	gfritzler@bresnan.net	left msg 9/21
, COGCC		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201286	WELL	PR	04/01/2020	OW	001-06689	LINNEBUR 4	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Unable to access well inside of elk farm.		
Corrective Action:	Provide key, combinations, or alternate method of access to comply with rule 204.	Date:	04/01/2021

Overall Good: ☒

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 201286 Type: WELL API Number: 001-06689 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: Fluid Type:

End Surf Csg Pressure:

Comment: No bradenhead test on file. Contact COGCC engineering.

04/09/2021

Corrective Action: Comply with COGCC annual bradenhead testing rules.

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On 3/31/21 at approximately 1300 I, Inspector Justin Medina conducted an on-site inspection at:
 Well Name- Linnebur 4
 Company Name- Fritzler Resources
 API- 05-001-06689
 In Adams County Colorado.
 While there, I observed unaccusable well
 No bradenhead test on file. Contact COGCC engineering.
 Comply with COGCC annual bradenhead testing rules.4/9/21
 Unable to access well inside of elk farm.
 Provide key, combinations, or alternate method of access to comply with rule 204.
 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

medinaj

04/01/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699502495	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391926