

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: shares containment with oil tank	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	200 BBLs	STEEL AST		

Comment: 210 BBL	
Corrective Action:	Date:

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 202952 Type: WELL API Number: 001-08357 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well has been shut in since 4/1/18 MIT is required per COGCC mechanical integrity testing rules. Contact COGCC Engineering.

Corrective Action: Well must be either:
1) Per COGCC Rule 326.b.(1) a successful mechanical integrity test shall be performed on each shut-in well within two (2) years of the initial shut-in date or
2) Be properly plugged and abandoned . Shut-in and temporarily abandoned wells must be properly reported on COGCC Form 7, Operator's Monthly Production Report. Date: 03/29/2021

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Annual bradenhead test is not current. Contact COGCC engineering. 04/08/2021

Corrective Action: Comply with COGCC annual bradenhead testing rules. Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 3/29/21 at approximately 1445 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Piland 15-3 Company Name- Piland Resources API- 05-001-07981 In Adams County Colorado. While there, I observed SI well. During this inspection the following possible compliance issues were observed: Trash and weeds on location see pics Comply with COGCC Housekeeping rules 4/29/21 Annual bradenhead test is not current. Contact COGCC engineering. Comply with COGCC annual bradenhead testing Rules 4/8/21 Well has been shut in since 6/1/18, needs MIT according to COGCC Mechanical Integrity Test rules. Well must be either: 1) Per COGCC Rule 326.b.(1) a successful mechanical integrity test shall be performed on each shut-in well within two (2) years of the initial shut-in date or 2) Be properly plugged and abandoned . Shut-in and temporarily abandoned wells must be properly reported on COGCC Form 7, Operator's Monthly Production Report. 3/29/21 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	03/29/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402643018	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5389282
699502432	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5389276