

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/08/2021

Submitted Date:

04/08/2021

Document Number:

700702544

FIELD INSPECTION FORMLoc ID 324112 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257412	WELL	PR	05/26/2000	GW	045-07560	CLOUGH RMV 239-29	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 4/6/2021 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RMV 239-29, at Location # 324112 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also within close proximity to 317.B. area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for tracking pad.

During this inspection the following possible compliance issues were observed:

1. Location show signs of lack of stabilization/compaction

2. Well head missing API #

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well head missing API #		
Corrective Action:	Comply with rule 605.d	Date:	05/07/2021

Emergency Contact Number:			
Comment:	911	Date:	
Corrective Action:		Date:	

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Braden heads have a port for manual gauge monitoring		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	257412	Type:	WELL	API Number:	045-07560	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Compaction	Fail					
		Ditches				

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also within close proximity to 317.B. area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for tracking pad.
1. Location show signs of lack of stabilization/compaction

Corrective Action: **Install or repair required BMPs**

Date: 05/07/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702551	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5398111