


APACHE CANYON 02-03 API# 05-071-08347 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 09, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103276

Inspection Photos

Location Name: APACHE CANYON 02-03
API#: 05-071-08347
INSP. #: 695103276

WILTED 2 YEAR COMMON MULLEIN WAS TREATED PRIOR TO INSPECTION



WILTED COMMON MULLEIN ROSETTES WERE TREATED PRIOR TO INSPECTION

WILTED COMMON MULLEIN ROSETTES WERE TREATED PRIOR TO INSPECTION




PHOTO 7: CLASS C NOXIOUS WEEDS ON AROUND LOCATION INCLUDING THE INTERIM RECLAMATION AREA. COMPLY WITH RULE 1003.f. CA DATE 9-23-20.

PHOTO 8: CLASS C NOXIOUS WEEDS ON AROUND LOCATION INCLUDING THE INTERIM RECLAMATION AREA. COMPLY WITH RULE 1003.f. CA DATE 9-23-20.



PHOTO 1: THE COMMON MULLEIN DEPICTED IN FIELD INSPECTION REPORT DOCUMENT # 695103276 PHOTOGRAPH # 7 AND # 8 ARE WILTED DUE TO WEED TREATMENT THAT OCCURRED THE WEEK OF 09/05/20. THE COGCC FIELD INSPECTION WAS CONDUCTED ON 09/11/20.

APACHE CANYON 02-03 API# 05-071-08347 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 09, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103276



COMMON MULLEIN ROSETTE



COMMON MULLEIN 2 YEAR
GROWTH HAS DIED.

PHOTO 2: THE COMMON MULLEIN FROM LAST YEAR HAVE DIED. OGRIS OPERATING WILL BEGIN SPRING WEED TREATMENT ONCE WEATHER CONDITIONS ARE FAVORABLE FOLLOWED BY FALL TREATMENT.

APACHE CANYON 02-03 API# 05-071-08347 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 09, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103276



PHOTO 3: THE IMPACTED SOIL/GRAVEL NEAR THE LIQUID RING COMPRESSOR AND AROUND THE LOCATION WERE CLEANED UP AND REMOVED FROM THE LOCATION.

APACHE CANYON 02-03 API# 05-071-08347 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 09, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103276



PHOTO 4: THE FLUID ACCUMULATION ON THE LIQUID RING COMPRESSOR SKID WAS CLEANED UP.

APACHE CANYON 02-03 API# 05-071-08347 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 09, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103276



PHOTO 5: THE IMPACTED SOIL ON LOCATION WAS REMOVED AND PROPERLY DISPOSED IN ACCORDANCE WITH THE OGRIS OPERATING WASTE MANAGEMENT PLAN.

APACHE CANYON 02-03 API# 05-071-08347 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 09, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103276



PHOTO 6: THE SCRUBBER LIQUID WAS REMOVED FROM THE PRODUCED WATER TANK AND DISPOSED OF PER OGRIS'S WASTE MANAGEMENT PLAN AND THE COGCC RULES AND REGULATIONS.