

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/13/2021

Submitted Date:

04/13/2021

Document Number:

700702578

**FIELD INSPECTION FORM**
 Loc ID 335443 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272678	WELL	PR	03/02/2005	GW	045-10129	BELL 34-4C (D34NE)	PR
272679	WELL	PR	03/07/2005	GW	045-10128	BELL 34-3C (D34NE)	PR
272683	WELL	PR	03/05/2005	GW	045-10130	BELL 34-4 (D34NE)	PR
272684	WELL	PR	02/28/2005	GW	045-10131	BELL 34-3 (D34NE)	PR

**General Comment:****COGCC Inspection Report Summary**

On Tuesday 4/13/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a follow up inspection at Caerus D34NE, at Location # 335443 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also location is within or in close proximity to the 411 water protection area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

C/A's from previous inspection document # 700702399 have been completed. Inventory of location remains the same.

During this inspection the following possible compliance issues were observed:

1. Tank battery signage does not meet requirements of rule 605.e

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	1. Tank battery signage does not meet requirements of rule 605.e		
Corrective Action:	Comply with rule 605.e	Date:	05/13/2021

**Emergency Contact Number:**

Comment:	911	Date:	
Corrective Action:			

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	272678	Type:	WELL	API Number:	045-10129	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	272679	Type:	WELL	API Number:	045-10128	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	272683	Type:	WELL	API Number:	045-10130	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	272684	Type:	WELL	API Number:	045-10131	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Culverts				
		Ditches				
Berms						
Compaction						

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also location is within or in close proximity to the 411 water protection area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls. C/A's from previous inspection document # 700702399 have been completed.

Corrective Action:

Date: \_\_\_\_\_

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702582	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5402390">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5402390</a>