

FORM  
INSPRev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/14/2021

Submitted Date:

04/14/2021

Document Number:

693505041

### FIELD INSPECTION FORM

Loc ID 336262 Inspector Name: Silver, Randy On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 3 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
	303-825-4822	cogcc@kpk.com	All inspections
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241692	WELL	PR	10/01/2018	OW	123-09481	MILTON H. NELSON UNIT C 1	SI

**General Comment:**

**Inspected Facilities**Facility ID: 241692 Type: WELL API Number: 123-09481 Status: PR Insp. Status: SI**Idle Well**Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: SICorrective Action: Date: **COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>  On 4-14-2021 at approximately 1:19PM, I Randy Silver, conducted an inspection of KPK well  API # 05-123-09481 in Weld County Colorado.  The purpose of this inspection was to confirm compliance with the COGCC Director's order under rule 901.a. of the Rules and Regulations of the Colorado Oil and Gas Conservation Commission, 2 CCR 404-1 ("Rule" or "Rules"). As part of this order the operator KPK (Operator No. 46290) was ordered to immediately suspend all production operations at these assigned location.</p> <p>I inspected this location and confirmed operations appeared to be suspended as equipment on site does appear to be shut off and valves appear to be closed. See attached photos in attachments of this inspection.</p> <p>On 4-14-2021 the operator KPK notified COGCC staff Jeremy Ferrin through email that all 87 locations listed in the order had suspended all production operations at these locations.</p> <p>All corrective action from previous and further inspection must be completed to comply with COGCC rules.  This is a summary of inspection report.</p>	silverr	04/14/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693505042	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5403509">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5403509</a>