

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/14/2021

Submitted Date:

04/14/2021

Document Number:

693505055

FIELD INSPECTION FORM
 Loc ID 318281 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
	303-825-4822	cogcc@kpk.com	All inspections
Leonard, Mike		mike.leonard@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241030	WELL	PR	08/01/2019	OW	123-08818	THOMAL L. RUSSELL 'D' 2	SI

General Comment:

Inspected FacilitiesFacility ID: 241030 Type: WELL API Number: 123-08818 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: SICorrective Action: Date: **COGCC Comments**

Comment

User

Date

COGCC Inspection Report Summary

On 4-14-2021 at approximately 3:12PM, I Randy Silver, conducted an inspection of KPK well

API # 05-123- 08818 in Weld County Colorado.

The purpose of this inspection was to confirm compliance with the COGCC Director's order under rule 901.a. of the Rules and Regulations of the Colorado Oil and Gas Conservation Commission, 2 CCR 404-1 ("Rule" or "Rules"). As part of this order the operator KPK (Operator No. 46290) was ordered to immediately suspend all production operations at these assigned location.

I inspected this location and confirmed operations appeared to be suspended as equipment on site does appear to be shut off and valves appear to be closed. See attached photos in attachments of this inspection.

On 4-14-2021 the operator KPK notified COGCC staff Jeremy Ferrin through email that all 87 locations listed in the order had suspended all production operations at these locations.

All corrective action from previous and further inspection must be completed to comply with COGCC rules.

This is a summary of inspection report.

silverr

04/14/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693505056	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5403516