

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/08/2021

Submitted Date:

04/08/2021

Document Number:

696303119

FIELD INSPECTION FORM

 Loc ID 424744 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10503
 Name of Operator: RED HAWK PETROLEUM LLC
 Address: 575 N DAIRY ASHFORD STE 201
 City: HOUSTON State: TX Zip: 77079
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
 2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
Boyd, William		wboyd@pedevco.com	All Inspections
Allison, Rick		rick.allison@state.co.us	
Shepard, DeAnn		dshepard@pedevco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424741	WELL	PR	11/01/2019	OW	123-34161	Staudinger 1-31H	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Wellhead Contact Number NOT Current		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	05/10/2021
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
Crude Oil	WELLHEAD	<= 1 bbl	
Comment:	Wellhead Actively leaking at the time of this Inspection. Pulled into Location to find spill at Wellhead. Called Contact number posted at Battery. Also called a Charles at 24 Hour Emergency Contact. To get Operator to shut-down well and stop the leak. Approximately 17' x 105' area of impacted soil.		
Corrective Action:	"Properly dispose of oily waste in accordance with Rule 905.e and contact area COGCC EPS"		Date: 04/10/2021

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Flare	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLs	STEEL AST		40.624400,-104.241990
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Field Flare		
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 424741 Type: WELL API Number: 123-34161 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 04/08/2021 at approximately 11:07, I, Inspector Erica Petrie, conducted a Follow-Up Field Inspection at Red Hawk Petroleum, LLC, Staudinger 1-31H, Location #424744 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this Inspection the following possible compliance issues were observed:</p> <p>Wellhead Actively leaking at the time of this Inspection. Pulled into Location to find spill at Wellhead. Called Contact number posted at Battery. Also called a Charles at 24 Hour Emergency Contact. To get Operator to shut-down well and stop the leak. Approximately 17' x 105' area of impacted soil. "Properly dispose of oily waste in accordance with Rule 905.e and contact area COGCC EPS" Corrective Action Date 05.10.2021</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection Report.</p>	petrie	04/08/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402653591	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5398730
696303120	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5398720