

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/15/2021

Submitted Date:

04/15/2021

Document Number:

693505085

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
 318368 _____ Silver, Randy _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: _____ 46290 _____
 Name of Operator: KP KAUFFMAN COMPANY INC _____
 Address: 1675 BROADWAY, STE 2800 _____
 City: _____ DENVER _____ State: _____ CO _____ Zip: _____ 80202 _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 3 _____ Number of Comments
 0 _____ Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,	303-825-4822	cogcc@kpk.com	All Inspections
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241178	WELL	PR	10/12/2000	OW	123-08966	UPRR 43 PAN AM I 15	SI

General Comment:

Inspected FacilitiesFacility ID: 241178 Type: WELL API Number: 123-08966 Status: PR Insp. Status: SI**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: SICorrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On 4-15-2021 at approximately 2:57PM, I Randy Silver, conducted an inspection of KPK well API # 05-123- 08966 in Weld County Colorado. The purpose of this inspection was to confirm compliance with the COGCC Director's order under rule 901.a. of the Rules and Regulations of the Colorado Oil and Gas Conservation Commission, 2 CCR 404-1 ("Rule" or "Rules"). As part of this order the operator KPK (Operator No. 46290) was ordered to immediately suspend all production operations at these assigned location.</p> <p>I inspected this location and confirmed operations appeared to be suspended as equipment on site does appear to be shut off and valves appear to be closed. See attached photos in attachments of this inspection.</p> <p>On 4-14-2021 the operator KPK notified COGCC staff Jeremy Ferrin through email that all 87 locations listed in the order had suspended all production operations at these locations.</p> <p>All corrective action from previous and further inspection must be completed to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	04/15/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693505086	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5404744