

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/15/2021

Submitted Date:

04/15/2021

Document Number:

693505089

FIELD INSPECTION FORM

Loc ID 318121 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
,	303-825-4822	cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240645	WELL	PR	01/01/2021	OW	123-08433	COSSLETT 3	SI

General Comment:

Inspected FacilitiesFacility ID: 240645 Type: WELL API Number: 123-08433 Status: PR Insp. Status: SI**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: SICorrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On 4-15-2021 at approximately 3:23PM, I Randy Silver, conducted an inspection of KPK well API # 05-123- 08433 in Weld County Colorado. The purpose of this inspection was to confirm compliance with the COGCC Director's order under rule 901.a. of the Rules and Regulations of the Colorado Oil and Gas Conservation Commission, 2 CCR 404-1 ("Rule" or "Rules"). As part of this order the operator KPK (Operator No. 46290) was ordered to immediately suspend all production operations at these assigned location.</p> <p>I inspected this location and confirmed operations appeared to be suspended as equipment on site does appear to be shut off and valves appear to be closed. See attached photos in attachments of this inspection.</p> <p>On 4-14-2021 the operator KPK notified COGCC staff Jeremy Ferrin through email that all 87 locations listed in the order had suspended all production operations at these locations.</p> <p>All corrective action from previous and further inspection must be completed to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	04/15/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693505090	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5404746