

**TEP ROCKY MOUNTAIN LLC**  
**FEDERAL-66S96W 36NWNW**  
**Location # 335189**



**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 36NWNW  
Location # 335189**





**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 36NWNW  
Location # 335189**



**Junk**



**Unmarked deadman**



**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 36NWNW  
Location # 335189**



**Unmarked deadman**



**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 36NWNW  
Location # 335189**



**Storm water in metal well cellar.**



**Storm water in metal well cellar.**



**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 36NWNW  
Location # 335189**



**Storm water in metal well cellar.**





**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 36NWNW  
Location # 335189**



**Oil filter on edge of location.**



**TEP ROCKY MOUNTAIN LLC**  
**FEDERAL-66S96W 36NWNW**  
**Location # 335189**





**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 36NWNW  
Location # 335189**



**Sediment build up in culvert.**





**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 36NWNW  
Location # 335189**



**Erosion of drainage ditch and around rip rap.**





**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 36NWNW  
Location # 335189**



**Sediment build in basin.**



**Erosion from check dam storm water flow.**



**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 36NWNW  
Location # 335189**



**Erosion of wall along road with 4" pipe .**



**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 36NWNW  
Location # 335189**



**Washing of road and ditches.**



**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 36NWNW  
Location # 335189**



**Rutted up road way.**



**Sediment build up in ditch.**



**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 36NWNW  
Location # 335189**



**Rutted up road.**



**Sediment build up in ditch.**



**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 36NWNW  
Location # 335189**



**Rutted up road.**



**Erosion of road into the ditch.**



**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 36NWNW  
Location # 335189**



**Rutted up road.**



**Fallen rock on road.**



**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 36NWNW  
Location # 335189**



**Sediment build up in ditch.**



**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 36NWNW  
Location # 335189**



**Culvert needs cleaned out and maintained.**



**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 36NWNW  
Location # 335189**



**Sediment build up in culvert pipe.**