



State 36-10
Remediation Plan for PA

Surface equipment removal to start 30-60 days before planned plugging operations by roustabout crew. All salvageable equipment will be moved to storage yard. Any equipment that is not salvageable will be disposed of properly.

Off location flowline abandoned per Rule 1105; abandoned in place per Rule 1105.d.(2).D, Rule 1105.e, and Rule 1105.f.

Final reclamation per Rule 1003 and Rule 1004.

Multiple soil samples taken at wellhead due to well location size, with one wellhead background sample. One soil sample taken at meter shed riser during abandonment. Meter shed location will not be abandoned due to multiple other wells metered at same location.

Remediation process will be done dependent on soil analysis.

Well location is checked monthly by Lease Attendant, EC readings taken approximately every 60 days, percent of vegetation regrowth monitored, any noticeable erosion and overall appearance of location.

If soil analysis determines or if EC readings do not drop, gypsum will be applied and/or site will be irrigated.

When soil analysis falls under allowable limits of Table 915-1, area will be seeded, straw is stitched in or manure applied, if necessary, and monitored for vegetation growth and erosion.

Closure request submitted after soil analysis falls under allowable limits of Table 915-1 and vegetation has acceptable growth.

Form 4 Sundry submitted for final reclamation inspection within 30 days of final Form 27 remediation approval.