

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402654588

Date Received:

04/11/2021

Spill report taken by:

NEIDEL, KRIS

Spill/Release Point ID:

447857

### SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

### OPERATOR INFORMATION

Name of Operator: <u>CHEVRON USA INC</u>	Operator No: <u>16700</u>	<b>Phone Numbers</b> Phone: <u>(970) 675-3814</u> Mobile: <u>(307) 871-5363</u> Email: <u>spwu@chevron.com</u>
Address: <u>100 CHEVRON ROAD</u>		
City: <u>RANGELY</u>	State: <u>CO</u> Zip: <u>81648</u>	
Contact Person: <u>Chris Patterson</u>		

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401117166

Initial Report Date: 09/22/2016 Date of Discovery: 09/22/2016 Spill Type: Recent Spill

#### Spill/Release Point Location:

QTRQTR NESE SEC 31 TWP 2N RNG 102W MERIDIAN 6

Latitude: 40.100500 Longitude: -108.880500

Municipality (if within municipal boundaries): \_\_\_\_\_ County: RIO BLANCO

#### Reference Location:

Facility Type: \_\_\_\_\_  Facility/Location ID No \_\_\_\_\_

Spill/Release Point Name: \_\_\_\_\_  Well API No. (Only if the reference facility is well) 05-103-09100

No Existing Facility or Location ID No.

#### Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

*Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): >=1 and <5 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): >=5 and <100

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: \_\_\_\_\_

#### Land Use:

Current Land Use: NON-CROP LAND Other(Specify): \_\_\_\_\_

Weather Condition: Clear and 70 degrees

Surface Owner: OTHER (SPECIFY) Other(Specify): Private Land

#### Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State  Residence/Occupied Structure  Livestock  Public Byway  Surface Water Supply Area

*As defined in COGCC 100-Series Rules*



## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure:  Corrective Actions Completed (documentation attached)

Work proceeding under an approved Form 27

Form 27 Remediation Project No: \_\_\_\_\_

### OPERATOR COMMENTS:

This area noted on the Form 19 was walked and soil was probed with a shovel to identify any notable impacts and assure that representative samples were collected initially on 11/3/2016. No hydrocarbon odors or salt staining were observed. The SS1 sample location was re-sampled on 8/19/20 for SAR and EC. The SS2 sample location was re-sampled on 4/1/21 for EC. All samples are now within the COGCC Table 910-1 allowable concentrations. Chevron is requesting closure of Spill Release Point 447857 under Table 910-1 due to the initial release occurring during Table 910-1 rule. Samples were collected prior to the Table 915 adoption

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Chris Patterson

Title: Lead ENV Specialist Date: 04/11/2021 Email: spwu@chevron.com

### Condition of Approval

#### COA Type

#### Description

1 COA	Based on review of information presented it appears that no further action is necessary at this time, and COGCC approves the closure request. However, should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if ground water is found to be impacted, then further investigation and/or remediation activities may be required at the site
-------	---

### Attachment List

#### Att Doc Num

#### Name

402654588	SPILL/RELEASE REPORT(SUPPLEMENTAL)
402654589	ANALYTICAL RESULTS
402661669	FORM 19 SUBMITTED

Total Attach: 3 Files

### General Comments

#### User Group

#### Comment

#### Comment Date

Environmental	It appears that natural attenuation was successful.	04/16/2021
---------------	---	------------

Total: 1 comment(s)