

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/14/2021

Submitted Date:

04/14/2021

Document Number:

699103392

FIELD INSPECTION FORMLoc ID 423766 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

7 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections
Kraich, Adam		adam.kraich@state.co.us	
Krautschun, Marty		mkrautschun@bonanzacrk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423776	WELL	TA	06/13/2019	GW	123-33713	Antelope 13-20	TA
423779	WELL	TA	06/13/2019	GW	123-33715	Antelope 14-20	TA

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Both well signs are not legible. See attached photos.		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	05/28/2021
Type	TANK LABELS/PLACARDS		
Comment:	NFPA placard on north crude oil tank is weathered See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	05/28/2021

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Tumbleweeds around wells need to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606	Date:	05/28/2021
Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment next to wells needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606	Date:	05/28/2021
Type	TRASH		
Comment:	Trash in multiple spots, needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606	Date:	05/28/2021
Type	OTHER		
Comment:	Stained soil around production tanks needs to be removed. See attached photos.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	05/28/2021
Type	DEBRIS		
Comment:	Cement debris needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606	Date:	05/28/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		

Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbwire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	BV CONCRETE		,	
Comment:	Shares containment with crude oil tanks					
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)	60 BBL	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	4	400 BBLS	STEEL AST		40.379800,-104.355100	
Comment:						
Corrective Action:				Date:		

Paint

Inspector Name: Burns, Adam

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 423776 Type: WELL API Number: 123-33713 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: T/A

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 09/24/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 423779 Type: WELL API Number: 123-33715 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: T/A

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 09/24/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 4/14/21 at approximately 0754hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Antelope 14-20 of Bonanza Creek Energy, at Location ID # 423766 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused equipment, needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/28/21.</p> <p>Tumbleweeds around wells need to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/28/21</p> <p>Trash in multiple spots, needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/28/21</p> <p>Cement debris needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/28/21</p> <p>Both well signs are not legible. Install sign to comply with Rule 605.g. With a corrective action date of 5/28/21.</p> <p>NFPA placard on north crude oil tank is weathered. Install sign to comply with Rule 605.g. With a corrective action date of 5/28/21.</p> <p>Stained soil around production tanks needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 5/28/21.</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	04/14/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402658675	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5403225
699103393	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5403220