

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/20/2021

Submitted Date:

04/21/2021

Document Number:

701500406

## FIELD INSPECTION FORM

 Loc ID: 316192  
 Inspector Name: Moran, Rick  
 On-Site Inspection:   
 2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 10 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**
 OGCC Operator Number: 200502  
 Name of Operator: 31 OPERATING  
 Address: 3021 RIDGE RD #156  
 City: ROCKWALL State: TX Zip: 75032
**Contact Information:**

Contact Name	Phone	Email	Comment
Ikenouye, Teri		teri.ikenouye@state.co.us	
Freeman, Kris	254-717-0435	kfreeman@31operating.com	
Boulger, Levin		lboulger@31operating.com	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	
Heil, John		john.heil@state.co.us	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Trujillo, Aaron		aaron.trujillo@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256078	WELL	TA	04/01/2001	GW	103-09976	PARKER 4-35	TA

**General Comment:**

A follow up inspection of documents:

- 1) 699700122 dated 4-15-2020.

The following compliance issues are uncompleted:

- 1) Submit eForm 19 for the spills. Photos 2 & 3. Complete by 5-15-2020.
- 2) Submit eForm 27 for the pit closure. Photo 4. Complete by 6-15-2020.

Additional compliance issues:

- 1) Well leaking oil & cleanup. Photos 2 & 3. Complete by 4-21-2021.
- 2) Bradenhead access is not present. Photo 2. Complete by 5-21-2021.
- 3) Production history not current.

Note: The wellhead is located approximately 105 feet north of the White River. The emergency phone 800-209-9762 was called on 4-20-2021 @ 16:33 to report the leak. Phone call was returned @ 17:54.

Location is within a Rule 1202.c Aquatic sportfish management area, and Rule 309.e.1 Bald eagle roost site.

This is a summary of inspection report 701500406.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
Crude Oil	WELLHEAD		
Comment:	Hydrocarbons are next to the well extending up to ~1 foot away and have soaked the ground > 2".		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: <u>04/21/2021</u>

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Other	#		
Comment:	The leak was observed in 2020 & during this inspection. Both spills need reported.		
Corrective Action:	Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff per Rule 912.b.		Date: <u>05/15/2020</u>
Type: Bradenhead	# 1		
Comment:	Bradenhead access is not present.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).		Date: <u>05/21/2021</u>

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 256078 Type: WELL API Number: 103-09976 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Last MIT on 4-5-2017.  
Last reported monthly operations were January 2021. Production is missing for July 2020 to September 2020. Most recent reported production Febuary 2002. Report past due monthly operations.  
Submit required Form 7(s) to COGCC per rule 413.a.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Other						Grass on location.

Comment: No significant soil migration; erosion or soil movement on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Drilling Pit                      Lined: NO                      Pit ID:                      Lat:                      Long:

Reference Point: \_\_\_\_\_                      Other: \_\_\_\_\_                      Length: \_\_\_\_\_                      Width: \_\_\_\_\_

**Lining:**

Liner Type:    Liner Condition:

Comment: No visible pipe going into pit. Native grass & vegetation in pit.

Corrective Action

Contact COGCC Reclamation staff regarding drilling pit closure per rules 911.a and 1003.d. Contact environmental staff regarding appropriate closure documentation regarding E&P waste and confirmation sampling and Form 27 request if needed.

Date: 06/15/2020

**Fencing:**

Fencing Type:    Fencing Condition:

Comment: No fencing.

Corrective Action

Date:

**Netting:**

Netting Type:    Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:                      Oil Accumulation: NO                      2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701500407	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5409548">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5409548</a>