

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/14/2021

Submitted Date:

04/16/2021

Document Number:

701500352

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 316585 _____ Moran, Rick _____ 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 200502
 Name of Operator: 31 OPERATING
 Address: 3021 RIDGE RD #156
 City: ROCKWALL State: TX Zip: 75032
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
 3 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Ikenouye, Teri		teri.ikenouye@state.co.us	
Thompson, Bud		BLThomps@BLM.gov	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	
Freeman, Kris	254-717-0435	kfreeman@31operating.com	
Boulger, Levin		lboulger@31operating.com	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286545	WELL	SI	11/08/2010	GW	103-10899	LOVE FEDERAL 17-21	SI

General Comment:

A follow up inspection of documents:

- 1) Warning letter 401815357 dated 10-31-2018.
- 2) FIR 679705474 dated 9-17-2019.
- 3) NOAV 402283787 dated 1-14-2020.
- 4) FIR 700402954 dated 8-17-2020.
- 5) FIR 700404280 dated 11-18-2020.

The following compliance issues are uncompleted:

- 1) Acquire MIT or plug well. Complete by 1-31-2019.

Additional compliance issues:

- 1) Debris on location. Photos 1 to 3. Complete by 5-1-2021.
- 2) No battery sign present. Photos 3 & 4. Complete by 6-16-2021.
- 3) Production history not current.

Location is within a Rule 1202.c Aquatic sportfish management area, Rule 1202.d Mule deer severe winter range area, Rule 1202.d Mule deer winter concentration area, and a Black bear area.

This is a summary of inspection report 701500352.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign not present.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	06/16/2021
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 800-209-9762

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Debris on location.		
Corrective Action:	Remove debris.	Date:	05/01/2021

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Other	#		
Comment:	Last reported monthly operations were January 2021. Production is missing for July 2020 to September 2020. Most recent reported hydrocarbon production November 2009. Report past due monthly operations. Submit required Form 7(s) to COGCC per rule 413.b.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead access present.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 286545 Type: WELL API Number: 103-10899 Status: SI Insp. Status: SI**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: _____Comment: Last recorded production November 2009. Last MIT on 9-18-2013.Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention. Date: 01/31/2019**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402661147	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5405461
701500353	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5405457