

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/20/2021

Submitted Date:

04/21/2021

Document Number:

701500406

FIELD INSPECTION FORM

 Loc ID: 316192
 Inspector Name: Moran, Rick
 On-Site Inspection:
 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Operator Information:
 OGCC Operator Number: 200502
 Name of Operator: 31 OPERATING
 Address: 3021 RIDGE RD #156
 City: ROCKWALL State: TX Zip: 75032
Contact Information:

Contact Name	Phone	Email	Comment
Trujillo, Aaron		aaron.trujillo@state.co.us	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Heil, John		john.heil@state.co.us	
Freeman, Kris	254-717-0435	kfreeman@31operating.com	
Ikenouye, Teri		teri.ikenouye@state.co.us	
Boulger, Levin		lboulger@31operating.com	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256078	WELL	TA	04/01/2001	GW	103-09976	PARKER 4-35	TA

General Comment:

A follow up inspection of documents:

- 1) 699700122 dated 4-15-2020.

The following compliance issues are uncompleted:

- 1) Submit eForm 19 for the spills. Photos 2 & 3. Complete by 5-15-2020.
- 2) Submit eForm 27 for the pit closure. Photo 4. Complete by 6-15-2020.

Additional compliance issues:

- 1) Well leaking oil & cleanup. Photos 2 & 3. Complete by 4-21-2021.
- 2) Bradenhead access is not present. Photo 2. Complete by 5-21-2021.
- 3) Production history not current.

Note: The wellhead is located approximately 105 feet north of the White River. The emergency phone 800-209-9762 was called on 4-20-2021 @ 16:33 to report the leak. Phone call was returned @ 17:54.

Location is within a Rule 1202.c Aquatic sportfish management area, and Rule 309.e.1 Bald eagle roost site.

This is a summary of inspection report 701500406.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:			
Type	Area	Volume	
Crude Oil	WELLHEAD		
Comment:	Hydrocarbons are next to the well extending up to ~1 foot away and have soaked the ground > 2".		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: <u>04/21/2021</u>

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Bradenhead access is not present.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).		Date: <u>05/21/2021</u>
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Other	#		
Comment:	The leak was observed in 2020 & during this inspection. Both spills need reported.		
Corrective Action:	Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff per Rule 912.b.		Date: <u>05/15/2020</u>

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 256078 Type: WELL API Number: 103-09976 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last MIT on 4-5-2017.
Last reported monthly operations were January 2021. Production is missing for July 2020 to September 2020. Most recent reported production Febuary 2002. Report past due monthly operations.
Submit required Form 7(s) to COGCC per rule 413.a.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other						Grass on location.
		Culverts				

Comment: No significant soil migration; erosion or soil movement on location.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Drilling Pit Lined: NO Pit ID: _____ Lat: _____ Long: _____

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: No visible pipe going into pit. Native grass & vegetation in pit.

Corrective Action

Contact COGCC Reclamation staff regarding drilling pit closure per rules 911.a and 1003.d. Contact environmental staff regarding appropriate closure documentation regarding E&P waste and confirmation sampling and Form 27 request if needed.

Date: 06/15/2020

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: No fencing.

Corrective

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective

Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: _____

Corrective

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402666779	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5409564
701500407	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5409548