

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/28/2021

Submitted Date:

04/29/2021

Document Number:

701500527**FIELD INSPECTION FORM**Loc ID 314430 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 100 CHEVRON ROADCity: RANGELY State: CO Zip: 81648**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Sanford, Anita		atlx@chevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228714	WELL	PR	01/01/1999	OW	103-05687	FEE 14	PR

General Comment:

This inspection identified an access road with tracking unto Rio Blanco County Rd 1 (Blue Mountain Hwy). Rainfall occurred ~36 hours earlier. The inspection is attached to the nearest well to the county road. The well location was not inspected.

The following compliance issues were identified:

- 1) Vehicle tracking unto county road.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	228714	Type:	WELL	API Number:	103-05687	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Vehicle Tracking	Fail	

Comment: [Tracking has occurred from the access road unto Rio Blanco County Rd 1. See attached photos.](#)

Corrective Action: [Install, maintain, or provide documentation of post construction management plan or BMP's.](#)

Date: 06/29/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701500528	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5416883