

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402682710

Date Received:

05/07/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10559

Name of Operator: SOUTHLAND ROYALTY COMPANY LLC

Address: 400 WEST 7TH STREET

City: FORT WORTH State: TX Zip: 76102

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Elgin, Jerry

jelgin@mspartners.com

Blaylock, Connie

cblaylock@mspartners.com

Gallenbeck, Danny

dgallenbeck@ctfieldsvcs.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689805646

Inspection Date: 04/09/2021

FIR Submit Date: 04/21/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: SOUTHLAND ROYALTY COMPANY LLC

Company Number: 10559

Address: 400 WEST 7TH STREET

City: FORT WORTH State: TX Zip: 76102

LOCATION - Location ID: 313308

Location Name: Landing Strip Unit-69N90W Number: 6NWSW County: MOFFAT

Qtrqr: NWS Sec: 6 Twp: 9N Range: 90W Meridian: 6

Latitude: 40.764000 Longitude: -107.539310

FACILITY - API Number: 05-081- -00 Facility ID: 285957

Facility Name: LANDING STRIP FEDERAL Number: 1

Qtrqr: NWS Sec: 6 Twp: 9N Range: 90W Meridian: 6

Latitude: 40.764000 Longitude: -107.539310

CORRECTIVE ACTIONS:

1 CA# 150238

Corrective Action: Calibrate gas metering equipment annually to comply with rule 430.d.(1).

Date: 05/21/2021

Response: CA COMPLETED

Date of Completion: 05/06/2021

Calibration of meter not performed because Form 6 NOI to P&A has been submitted and has been approved by

Operator Comment: the BLM. The P&A will be done in place of meter calibration.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**2** CA# 150240

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 05/21/2021

Response: CA COMPLETED

Date of Completion: 05/06/2021

Operator Comment: BMPs were not repaired due to well will be plugged and abandoned.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**3** CA# 150556

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 05/21/2021

Response: CA COMPLETED

Date of Completion: 05/06/2021

Operator Comment: Well will be plugged and abandoned.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Regarding Bradenhead access: Bradenhead valve has been dug up and piped to above ground level and a new valve installed with a gauge - 0 pressure on surface casing. Left exposed so pressure can be monitored.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Connie Blaylock

Signed: \_\_\_\_\_

Title: Regulatory Compliance

Date: 5/7/2021 10:44:25 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402682735	Submitted Form 6 NOI to P&A
-----------	-----------------------------

402682738	Photos of Bradenhead
-----------	----------------------

Total Attach: 2 Files