

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2021

Submitted Date:

05/10/2021

Document Number:

693700780**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
ALLISON, RICK 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452946	SPILL OR RELEASE	CL	01/09/2019		-	Sandy Hills Spreadfield	EI
454016	SPILL OR RELEASE	CL	01/09/2019		-	Sandy Hill 5-61-29	EI
455617	SPILL OR RELEASE	CL	01/09/2019		-	Sandy Hill 5-61-29	EI
455618	SPILL OR RELEASE	CL	01/09/2019		-	Sandy Hill 5-61-29	EI

**General Comment:**

**Inspected Facilities**

Facility ID: <u>452946</u>	Type: <u>SPILL OR</u>	API Number: <u>-</u>	Status: <u>CL</u>	Insp. Status: <u>EI</u>
Facility ID: <u>454016</u>	Type: <u>SPILL OR</u>	API Number: <u>-</u>	Status: <u>CL</u>	Insp. Status: <u>EI</u>
Facility ID: <u>455617</u>	Type: <u>SPILL OR</u>	API Number: <u>-</u>	Status: <u>CL</u>	Insp. Status: <u>EI</u>
Facility ID: <u>455618</u>	Type: <u>SPILL OR</u>	API Number: <u>-</u>	Status: <u>CL</u>	Insp. Status: <u>EI</u>

**Environmental****Spill/Remediation:**

Comment: Followup to Remediation Project#11244. Site has not been reclaimed, no evidence of seeding present. Operator submitted Form 27 Supplemental to request closure of Remediation Project. Operator must submit a Reclamation plan pursuant to Rule 915.b. to leave elevated levels of EC in place. In addition, Operator must stabilize location and perform reclamation prior to Remediation Project closure.

Corrective  
Action:

Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700781	SandyHillPhotos5-21-2021	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5424696">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5424696</a>