

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/05/2021

Submitted Date:

05/13/2021

Document Number:

700300135

FIELD INSPECTION FORM

Loc ID 325310 Inspector Name: LABOWSKIE, STEVE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 31250
Name of Operator: FRITZ & DIGMAN INC
Address: PO BOX 70024
City: ALBUQUERQUE State: NM Zip: 87197-

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Engineering		dnr_cogccengineering@state.co.us	
Digman, Bernie	575-640-1867	berniekdigman@gmail.com	
Fields, Vanessa		vanessa@walsheng.com	
Andrews, Vern		vern@walsheng.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214538	WELL	PR	08/01/2020	OW	067-06141	DAKOTA FEE 1	PR

General Comment:

[Also see 5/5/21 reclamation inspection Doc#693903152](#)

Location			
Lease Road:			
Type			
comment:	see 5/5/21 reclamation inspection		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text"/>		Date: _____
Corrective Action:	<input type="text"/>		
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	oily non servicable parts/valve stored inside pumpjack frame (see photo)		
Corrective Action:	remove non-servicable parts/parts not necessary for ongoing operations		Date: <u>06/01/2021</u>
Type	OTHER		
Comment:	stuffing box leak reapiired and free oil no longer present, some impacted material removed, some discolored saturated soil with odor still remains/observed with shovel test. Note" valve on end of vertical riser near wellhead with slight leak of crude oil		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Bradenhead	# 1		
Comment:	Operator emailed scanned Form 17 but has yet to upload them electronically. Note: monthly pressure monitroing and record keeping is also required per Rule 419		
Corrective Action:			Date:
Venting:			

Yes/No	YES		
Comment:	casing gas running through above ground flowline to flare device. Form 4 approved for vent/flare in 2019		
Corrective Action:		Date:	

Flaring:

Type	Other		
Comment:	converted fire tube burning gas		
Corrective Action:	Submit new sundry notice for vent/flare/combust per Rule 903.d(3)	Date:	<u>06/01/2021</u>

Inspected Facilities

Facility ID: 214538 Type: WELL API Number: 067-06141 Status: PR Insp. Status: PR

