

APACHE CANYON 11-06 API# 05-071-08297 & APACHE CANYON 11-06V API# 05-071-09276 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: MAY 14, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103368



PHOTO 1: THE IMPACTED SOIL NEAR THE RISERS WAS REMOVED AND PROPERLY DISPOSED IN ACCORDANCE WITH THE OGRIS OPERATING WASTE MANAGEMENT PLAN.



APACHE CANYON 11-06 API# 05-071-08297 & APACHE CANYON 11-06V API# 05-071-09276 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: MAY 14, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103368



PHOTO 2: THE IMPACTED SOIL NEAR THE ENGINE SKID WAS REMOVED AND PROPERLY DISPOSED IN ACCORDANCE WITH THE OGRIS OPERATING WASTE MANAGEMENT PLAN.



APACHE CANYON 11-06 API# 05-071-08297 & APACHE CANYON 11-06V API# 05-071-09276 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: MAY 14, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103368



PHOTO 3: THE IMPACTED SOIL NEAR THE LIQUID RING COMPRESSOR WAS REMOVED AND PROPERLY  
DISPOSED IN ACCORDANCE WITH THE OGRIS OPERATING WASTE MANAGEMENT PLAN.



APACHE CANYON 11-06 API# 05-071-08297 & APACHE CANYON 11-06V API# 05-071-09276 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: MAY 14, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103368



**PHOTO 4:** THE RISER'S ARE ACTUALLY A LOW PRESURE BY-PASS THAT ARE IN USE. EACH RISER WAS LABELED AS TO IT'S FUNCTION.



APACHE CANYON 11-06 API# 05-071-08297 & APACHE CANYON 11-06V API# 05-071-09276 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: MAY 14, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103368




PHOTO 5: RISERS ARE LABELED.



APACHE CANYON 11-06 API# 05-071-08297 & APACHE CANYON 11-06V API# 05-071-09276 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: MAY 14, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103368



PHOTO 6: THE OIL ACCUMULATION WAS REMOVED FROM THE CONTAINMENT OF THE LIQUID RING COMPRESSOR.



APACHE CANYON 11-06 API# 05-071-08297 & APACHE CANYON 11-06V API# 05-071-09276 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: MAY 14, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103368



PHOTO 7: THE OIL LEAK WAS REPAIRED, ALL CONECTIONS ARE SECURELY FASTEN.