

NEW ELK 35-13 API# 05-071-07990 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: MAY 14, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103940



PHOTO 1: THE FLUID ACCUMULATION THAT WAS FOUND INSIDE OF THE CONTAINMENT SKID OF THE LIQUID RING COMPRESSOR WAS REMOVED.