

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/19/2021

Submitted Date:

05/19/2021

Document Number:

693505165

FIELD INSPECTION FORMLoc ID 318936 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,	303-825-4822	cogcc@kpk.com	All Inspections
,		dnr_cogccenforcement@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242539	WELL	SI	02/01/2021	GW	123-10330	OPAL 14-34 (1)	SI

General Comment:

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	11/13/2020

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Flowline and Crude Oil Transfer Line Statuses. (marking and LOTO)		
Corrective Action:	Comply with rule 1101 a	Date:	11/13/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		
Comment:	Production facility is clearly visible from a public highway, road, or publicly-maintained trail. Facility paint is not uniform, non-contrasting, non-reflective color tones (similar to the Munsell Soil Color Coding System), and with colors matched to but slightly darker than the surrounding landscape.				
Corrective Action:	Paint production facilities per Rule 425.				Date: 11/13/2020

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Inspected FacilitiesFacility ID: 242539 Type: WELL API Number: 123-10330 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: SICorrective Action: Date: **COGCC Comments**

Comment

User

Date

COGCC Inspection Report Summary

On Wednesday May 19, 2021 at approximately 10:amM, I, Inspector Randy Silver, conducted an on-site inspection follow up inspection due to complaint..

Location: Opal 14-34

Operator: KP Kauffman

API#: 05-123-10330

County: Weld

While there, I observed well site and production facility.

During this inspection the following possible compliance issues were observed:

Unmarked risers: Rule 1101 a Corrective action date of 11-13-20

Placards: Rule 605 h Corrective action date of 11-13-20

Visual impact: Rule 425 Corrective action date of 11-13-20

Inspection due to complaint Doc#200449719 and follow up inspection to doc#693503280.

At time of inspection I did several corective actions had been completed and some that still hove not.

Weather conditions: Clear and dry

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

silverr

05/19/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693505166	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5438941