

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402698307

Date Received:
05/24/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Petrie, Erica</u>		<u>NBL_DJBU_Inspections@NBLENERGY.COM</u> <u>erica.petrie@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 697502389

Inspection Date: 01/05/2021

FIR Submit Date: 01/05/2021

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 422552

Location Name: KUMMER PC LE Number: 23-17 County: _____

Qtrqtr: SENE Sec: 23 Twp: 8N Range: 61W Meridian: 6

Latitude: 40.648980 Longitude: -104.167730

FACILITY - API Number: 05-123-00 Facility ID: 422552

Facility Name: KUMMER PC LE Number: 23-17

Qtrqtr: SENE Sec: 23 Twp: 8N Range: 61W Meridian: 6

Latitude: 40.648980 Longitude: -104.167730

CORRECTIVE ACTIONS:

1 CA# 145682

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Revegetation activities shall be complete no later than 4/12/2021 or as soon as environmental conditions will permit.

Date: 04/12/2021

Response: CA COMPLETED

Date of Completion: 05/11/2021

Operator Comment: Once we received the inspection we met with the landowner and the COGCC inspector withing the following week to align on a plan and have recently finished the last step for the corrective actions with seeding. We additionally added a tackifier in efforts to mitigate wind erosion that is common in this area until the growth is able to establish and take place. This location also will be included in our reclamation inspection program and we will be able to be proactive to address concerns that may arise. A fence was also installed around the perimeter to mitigate cattle until growth is established.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Alan Figurski Signed: _____

Title: WSS Date: 5/24/2021 9:11:06 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402698307	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files