

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/26/2021

Submitted Date:

05/27/2021

Document Number:

699803156

FIELD INSPECTION FORM

Loc ID 312689 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269798	WELL	PR	10/18/2018	GW	077-08797	ESPERANZA RANCH 2	PR

General Comment:

[COGCC Inspection Report Summary](#)
 On Wednesday 5/26/21 at approximately 14:00 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at LARAMIE ENERGY LLC Esperanza Ranch /2 Pad, Location #312689 in Mesa County Colorado.
 While there, I observed normal production operations.
 During this inspection the following compliance issues were observed:

- 1) No battery sign located at the tank battery with a corrective action date of 8/26/21.
- 2) Location lacks stabilization. No form of tracking BMP at entrance to location with a corrective action date of 6/10/21.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	No battery sign located at the tank battery.		
Corrective Action:	A permanent, conspicuous sign will be located at the tank battery.	Date:	08/26/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911/970-248-0497		Date:
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Livestock panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		

Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	All meter runs have been calibrated in the last year.		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 269798 Type: WELL API Number: 077-08797 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams				
Other	Fail					No form of tracking BMP at entrance to location.
		Culverts				
		Ditches				
Sediment Traps						
Gravel	Fail					Gravel insufficient
Compaction	Fail					Location lacks stabilization.
		Compaction				
		Gravel				
		Berms				
		Sediment Traps				
Berms						
Ditches						

Comment: Location lacks stabilization. No form of tracking BMP at entrance to location.

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations.

Date: 06/10/2021

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Signs/Markers and Storm water for corrective actions.	depaoloc	05/26/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699803157	Photos for Insp. #699803156	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5442239