

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/26/2021

Submitted Date:

05/27/2021

Document Number:

690201585**FIELD INSPECTION FORM**Loc ID 324493 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 66561Name of Operator: OXY USA INCAddress: PO BOX 27757 #110City: HOUSTON State: TX Zip: 77227-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
MONTGOMERY KELLEY		kelley_montgomery@oxy.com	
Kosola, Jason		jason.kosola@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211777	WELL	IJ	06/15/2015	DSPW	055-06012	GARCIA (EPA) 1-WD	RI

General Comment:

This is a location and stormwater management inspection.
See attached photos and additional details within this report.

Location

Lease Road:			
Type	Main		
comment:	It appears there was a recent high precipitation event that caused issues on the road. It appear the road was in process to be fixed but was not yet completed.		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:				
Type	Area	Volume		
Crude Oil	Tank			
Comment:	There is oil stained soils near the tank contained inside the bermed area. The oil stained soil needs to be cleaned up. This issues was previously observed during past inspections. No active leaks were observed but equipment needs to be inspected for mechanical integrity to prevent leaks from occurring.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608..			Date: 06/30/2021

In Containment: Yes

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is an area along the side of the road that is eroding which will need BMP's.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 06/30/2021

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690201586	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5442558