

**TEP ROCKY MOUNTAIN LLC
FEDERAL-67S96W 11NWNE
Location # 334982**



No battery sign at tank battery

**TEP ROCKY MOUNTAIN LLC
FEDERAL-67S96W 11NWN
Location # 334982**



Sediment build up on velocity checks.

**TEP ROCKY MOUNTAIN LLC
FEDERAL-67S96W 11NWNE
Location # 334982**



Sediment build up on velocity checks and storm water washing around.



Erosion of road into ditch.

**TEP ROCKY MOUNTAIN LLC
FEDERAL-67S96W 11NWNE
Location # 334982**



Erosion of road into ditch.



Sediment build up in ditch.

**TEP ROCKY MOUNTAIN LLC
FEDERAL-67S96W 11NWNE
Location # 334982**



Storm water crossing road at "Y" and eroding the shoulder around culvert.