

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/01/2021

Submitted Date:

06/01/2021

Document Number:

699803178

**FIELD INSPECTION FORM**Loc ID 415597 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

17 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus		COGCC.inspections@caerus oilandgas.com	

**General Comment:****COGCC Inspection Report Summary**

On Tuesday 6/1/21 at approximately 13:00 hours, I, Inspector Corey De Paolo,  
Conducted an on-site inspection at CAERUS PICEANCE LLC Orchard Unit /21-3 (F21OU),  
Location #415597 in Mesa County Colorado.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- 1) No battery sign located at the tank battery with a corrective action date of 9/1/21.
- 2) Location lacks stabilization. No form of tracking BMP at entrance to location with a corrective action date of 6/16/21.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the  
Compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No battery sign located at the tank battery.		
Corrective Action:	A permanent, conspicuous sign will be located at the tank battery.	Date:	09/01/2021

Emergency Contact Number:

Comment: 911/866-580-9382

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:	Summit midstream		
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Trash bins		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Generator		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Injection well		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Pressure transducer located on braden head. All braden head valves are accessible.		

Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Rig heater		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	8	500 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:	Date:		

**Flaring:**

Type			
Comment:			
Corrective Action:	Date:		

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps						
				Material Handling And Spill Prevention		Chemical tanks
		Sediment Traps				
Gravel	Fail					Gravel insufficient
		Ditches				
Ditches						
		Compaction				
Compaction	Fail					Location lacks stabilization
		Culverts				
		Gravel				
		Berms				
Other	Fail					No form of tracking BMP at entrance to location.
Berms						

Comment: Location lacks stabilization. No form of tracking BMP at entrance to location.

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations.

Date: 06/16/2021

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<u>Refer to Signs/Markers and Storm water for corrective actions.</u>	depaoloc	06/01/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699803179	Photos for Insp. #699803178	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445147">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445147</a>