

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402663339

Date Received:

04/19/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Mack, Ronald</u>		<u>rmack@ogrisop.com</u>
<u>Atwater, Bonnie</u>	<u>432-755-0212</u>	<u>batwater@ogrisop.com</u>
<u>Fitzgerald, Edie</u>	<u>719-859-1394</u>	<u>efitzgerald@ogrisop.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695103944

Inspection Date: 02/02/2021

FIR Submit Date: 02/02/2021

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 308462

Location Name: NEW ELK-633S68W Number: 35NWNE County: LAS ANIMAS

Qtrqtr: NWNE Sec: 35 Twp: 33S Range: 68W Meridian: 6

Latitude: 37.131270 Longitude: -104.964800

FACILITY - API Number: 05-071- -00 Facility ID: 272452

Facility Name: NEW ELK Number: 35-02

Qtrqtr: NWNE Sec: 35 Twp: 33S Range: 68W Meridian: 6

Latitude: 37.131270 Longitude: -104.964800

CORRECTIVE ACTIONS:

1 ☒ CA# 146253

Corrective Action: COMPLY WITH RULE 1002.f. AND Comply with general provisions of the oil and gas act for wildlife protection. AND SB-181. 24 HOURS TO STOP THE SPILL.

Date: 02/03/2021

Response: CA COMPLETED

Date of Completion: 02/02/2021

THE SCREW COMPRESSOR WAS SHUT IN IMMEDIATELY TO STOP FURTHER LEAKS. THE LEAK ON THE COMPRESSOR WAS REPAIRED. ONCE THE SNOW MELTED AND THE GROUND THAWED (APRIL 15,

Operator Comment: 2021)THE IMPACTED SOIL NEAR THE COMPRESSOR WAS CLEANED UP AND REMOVED FROM LOCATION.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. SEE ATTACHED PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: Sr. Environmental Tech.

Date: 4/19/2021 2:50:07 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402663339	FIR RESOLUTION SUBMITTED
402663351	PHOTO LOG

Total Attach: 2 Files