

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/09/2021

Submitted Date:

06/09/2021

Document Number:

693505196

FIELD INSPECTION FORM

Loc ID 319792 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,	303-825-4822	cogcc@kpk.com	All Inspections
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201392	WELL	PR	03/01/2017	OW	001-06795	ZARLENGO 1	PR

General Comment:

Inspected Facilities

Facility ID: 201392 Type: WELL API Number: 001-06795 Status: PR Insp. Status: PR

Complaint

Comment: Inspection in response to complaint.
 Field Inspector Assigned: Randy Silver
 Complaint Received
 Date: 6-1-2021
 Complaint Contacted: Yes via phone.
 Date: 6-2-2021 Time: 10:11AM
 Location ID #319792
 Location name: Zarlengo #1
 Inspection Document # 693505193
 Complaint inspection document# 695505196
 Complaint Document #200449731
 Nature of Complaint: Noise
 Field Inspector Actions:
 On 6-1-2021, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to noise. The complainant Todd Schulz 16654 Poplar Ct Brighton CO stated the issues were occurring outside of complainants home.
 On 6-2-2021, I attempted to make contact with the complainant who indicated that on 5-31-2021 he stated hearing noise form a pump jack that ran continuously 24/7 to the east of his residence.
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I performed a sound study. I could not set up a 24 hr study due to livestock in property. I performed a 1 HR test 350ft from the Pumping motor between source of noise and residents home. At time of inspection, sound levels were within COGCC rules.
 Weather conditions: Clear
 No violation of COGCC rules were observed at the time of the inspection.
 All information reviewed and site inspection information has been submitted to the COGCC for further review.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Complaint inspection.	silverr	06/09/2021