

APACHE CANYON 19-12 API# 05-071-06347 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672- DATE: JUNE 21, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201257



**PHOTO 1:** THE SEDIMENT ACCUMULATION WAS REMOVED FROM THE BAR DITCH AND THE DITCH WAS DOMINATED TO RECEIVE STORMWATER.



APACHE CANYON 19-12 API# 05-071-06347 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672- DATE: JUNE 21, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201257



**PHOTO 2:** THE SEDIMENT ACCUMULATION WAS REMOVED FROM THE CULVERT INLET. THE BAR DITCH WAS DOMINATED TO RECEIVE STORMWATER AND DIRECT THE FLOW TO THE CULVERT INLET. THE SEDIMENT ACCUMULATION WAS REMOVED FROM THE CULVERT INLET.



APACHE CANYON 19-12 API# 05-071-06347 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672- DATE: JUNE 21, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201257



**PHOTO 3:**THE BAR DITCH WAS DOMINATED TO RECEIVE STORMWATER AND DIRECT THE FLOW TOWARD THE CULVERT INLET. THE LEASE ROAD WAS CROWNED TO ESTABLISH SHEET FLOW OFF OF THE ROAD SURFACE AND ELIMINATE THE TIRE RUTS.



APACHE CANYON 19-12 API# 05-071-06347 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672- DATE: JUNE 21, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201257



**PHOTO 4:**THE BAR DITCH WAS DOMINATED TO RECEIVE STORMWATER FROM THE MAIN LEASE ROAD ON SOUTH FORK.