

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402726555

Date Received:  
06/23/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10383  
Name of Operator: SOVEREIGN OPERATING COMPANY LLC  
Address: P O BOX 370549  
City: DENVER State: CO Zip: 80237

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>THOMAS METZGER</u>		<u>tmetzger@bsegllc.com</u>
<u>Ryan Dornbos</u>		<u>ryan@PEOperating.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 690201511  
Inspection Date: 05/05/2021 FIR Submit Date: 05/07/2021 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: SOVEREIGN OPERATING COMPANY LLC Company Number: 10383  
Address: P O BOX 370549  
City: DENVER State: CO Zip: 80237

LOCATION - Location ID: 321018

Location Name: COMMERCE RANCH INC. 'B'- 631S42W Number: 18CSE County: BACA  
Qtrqr: CSE Sec: 18 Twp: 31S Range: 42W Meridian: 6  
Latitude: 37.340620 Longitude: -102.190770

FACILITY - API Number: 05-009-00 Facility ID: 205800

Facility Name: COMMERCE RANCH INC. 'B' Number: 1  
Qtrqr: CSE Sec: 18 Twp: 31S Range: 42W Meridian: 6  
Latitude: 37.340620 Longitude: -102.190770

CORRECTIVE ACTIONS:

1  CA# 150795

Corrective Action: Comply with 1004 Rules. Date: 07/31/2021

Response: CA COMPLETED Date of Completion: 06/14/2021

Operator Comment: Landowner was contacted to determine timing of crop harvest and treatment of surface. After the late summer harvest, the areas with low growth will be disked and organic material added to aid in the next planting season of spring 2022.

COGCC Decision: **Not Approved**

COGCC Representative: Corrective action has yet not been completed and this appears to be notification only. Please resubmit FIRR once the Corrective action is complete.

Additional reclamation may need to be performed to re-establish crop cover; including but not limited to soil testing, decompaction, amendments, removal and addition of new topsoil, ect.

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ryan Dornbos

Signed: \_\_\_\_\_

Title: Petroleum Engineer

Date: 6/23/2021 1:39:51 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

402726555	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files