

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/30/2021

Submitted Date:

07/09/2021

Document Number:

689805982

FIELD INSPECTION FORM

Loc ID: 312922 Inspector Name: Waldron, Emily On-Site Inspection: 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10677
Name of Operator: WOLVERINE RESOURCES LLC
Address: 109 EAST 17TH STREET #430
City: CHEYENNE State: WY Zip: 82001

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 6 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Reeves, Shane		shane@wolverineresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222842	WELL	SI	02/01/2019	DSPW	081-06202	BIGHOLE-FEDERAL 10-1	SI

General Comment:

Routine UIC inspection. Follow up to inspection from 6/4/2020 document number 689804299 and inspection from 4/30/2020 document number 689804085. No corrective actions appear to have been made.
Compliance issues:
previous operator on location signs
no emergency contact information for current operator on location
well is overdue for MIT
no bradenhead access apparent

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Signs on location still list HRM Resources as the operator. No current operator information, including emergency contact, on location.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	05/29/2020

Emergency Contact Number:

Comment:	No emergency contact information on location for current operator.		
Corrective Action:	Install sign to comply with Rule 605.	Date:	05/29/2020

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#		corrective date
Bradenhead			
Comment:	Bradenhead inaccessible or not visible		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)		Date: 07/19/2021

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 222842 Type: WELL API Number: 081-06202 Status: SI Insp. Status: SI

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube:	Pressure or inches of Hg _____ (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg _____	Previous Test Pressure _____	Inj Zone: <u>FTUN</u>
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	Last MIT: <u>09/22/2016</u>
			AnnMTReq: _____

Comment: No current Mechanical Integrity Test (MIT) on record or delinquent as required by Rule 417.a.(1)
Last MIT 9/22/2016 document number 401117842.

Corrective Action: Perform MIT per Rule 417.a. (1) Date: 07/19/2021

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689805983	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5475757