

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /31SWSE

Location ID: 334917



Photo #4404 from entrance to location.



Photo #4405 Well head sign weathered and not legible.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /31SWSE

Location ID: 334917



Photo #4406 Location lacks stabilization.



Photo #4407 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /31SWSE

Location ID: 334917



Photo #4408 No form of tracking BMP located at the entrance to location.