

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/08/2021

Submitted Date:

07/09/2021

Document Number:

700702950

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 316151 _____ Ramsey, Scott _____ 2A Doc Num: _____
Operator Information:

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

1 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
clark, Erin	405-319-3250	erin.k.clark@exxonmobil.com	Lead regulatory coordinator
Dooling, Jessica	832-624-0810	jessica.dooling@exxonmobil.com	
, Caerus		COGCC.inspections@caerusoilandgas.com	
Sutton, Derek		derek_sutton@xtoenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232244	WELL	PR	05/31/2012	GW	103-09915	LOVE RANCH FEE 1	PR

General Comment:**COGCC Inspection Report Summary**

On Thursday 7/8/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at XTO/Caerus Love Ranch #1, at Location # 316151 in Rio Blanco county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Well head cellars do not provide egress for wildlife
Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:			corrective date
Type: Pig Station	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	one (1) chemical tank in a metal containment and One (1) 500 gallon diesel tank in a metal containment		
Corrective Action:			Date:
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:			Date:

Type: Plunger Lift	# 1	
Comment:	Well head cellars do not provide egress for wildlife.	
Corrective Action:	Install means of egress or eliminate wildlife access.	Date: 08/09/2021
Type: Other	# 1	
Comment:	storage conex	
Corrective Action:		Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 232244 Type: WELL API Number: 103-09915 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Ditches						
Berms						
		Culverts				

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402743526	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5475635
700702963	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5475615