

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/08/2021

Submitted Date:

07/15/2021

Document Number:

697503057**FIELD INSPECTION FORM**Loc ID 452516 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10611Name of Operator: LONGS PEAK RESOURCES LLCAddress: 2727 ALLEN PARKWAY SUITE 1850City: HOUSTON State: TX Zip: 77019**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		angie.galvan@boomtownoil.com	
		egeiser@juncap.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452516	LOCATION	AC			-	Oxnard East 0607-8CH	RI

General Comment:

This is a follow up Interim Reclamation and Stormwater inspection from the previous Field Inspection Report Doc# 697500778 back on 11/4/2019.

Operator shall comply with all of the previous corrective actions from Field Inspection Report Doc# 679603858 submitted on 5/4/2021.

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ Fail _____

Comment _____

This location does not comply with Reclamation rules. Rule 1002.c. states all stockpiled soils shall use best management practices to prevent weed establishment.

The stockpile has significant weed cover- Russian thistle and Kochia- with little to no perennial vegetation that would compete with the weedy vegetation and generally work to decrease weed growth. Refer to the attached inspection photos.

Corrective Action _____

Comply with Rule 1002.c. to reseed the stockpile using the approved seed mixture (refer to Photo 7). Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management.

Since it is not ideal to perform seeding operations during the hot, summer months, revegetation activities shall be complete no later than 11/15/21 or as soon as environmental conditions will permit.

Date **11/15/2021**

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? <u>Pass</u>	Production areas stabilized ? <u>Pass</u>
1003c. Compacted areas have been cross ripped? _____	
1003d. Drilling pit closed? _____	Subsidence over on drill pit? _____
Cuttings management: _____	
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail	
Production areas have been stabilized? _____	Segregated soils have been replaced? _____
RESTORATION AND REVEGETATION	
<u>Cropland</u>	
Top soil replaced _____	Recontoured _____ Perennial forage re-established _____
<u>Non-Cropland</u>	
Top soil replaced _____	Recontoured _____ 80% Revegetation _____
1003e. INTERIM VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	
1003 f. Weeds Noxious weeds? _____	
Comment	After two growing seasons, there is a lack of desirable plant species throughout the interim reclamation areas. Interim reclamation areas are comprised mostly of undesirable, weedy chenopods.
Corrective Action	Perform reclamation in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use the approved seed mixture (refer to Photo 7). Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management. Since it is not ideal to perform seeding operations during the hot, summer months, revegetation activities shall be complete no later than 11/15/21 or as soon as environmental conditions will permit.
Date <u>11/15/2021</u>	
Overall Interim Reclamation <u>Fail</u>	
<u>Final Reclamation/ Abandoned Location:</u>	
Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____	
Final Land Use: <u>RANGELAND</u>	
Reminder: _____	
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	
Well plugged _____	Pit mouse/rat holes, cellars backfilled _____
Debris removed _____	No disturbance /Location never built _____
Access Roads _____	Regraded _____ Contoured _____ Culverts removed _____
Gravel removed _____	
Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____	
Compaction alleviation _____ Dust and erosion control _____	
Non cropland: Revegetated 80% _____	Cropland: perennial forage _____
Weeds present _____	Subsidence _____
1004.d. FINAL VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [At the time of this inspection, no erosion issues were observed.](#)

Corrective Action: _____

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402748628	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5479587
697503058	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5479584